Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

17" CHROME WHEEL CORROSION

Last Issued: 08/14/2001

APPLICABLE MODEL(S)/VIN

All 1999-2001 Millenia with VINs lower than JM1 TA22**** 718366.

DESCRIPTION

Under severe conditions, 17" chrome wheels may exhibit corrosion or pitting. As a mass-production change, the following three counter measures have been implemented: chrome plating thickness has been increased, inner wheel surface has been modified, and a corrosion prohibiting agent has been applied to the wheel surface.

Customers having this concern should have their vehicle repaired using the following procedure.

REPAIR PROCEDURE

- 1. Verify customer concern.
- 2. Replace affected wheel(s).
- 3. Verify repair.

PART(S) INFORMATION

Part Number	Description	Qty.	Notes
9965-02-7070	17" Chrome Wheel	1	Опly replace affected wheel(s)

WARRANTY INFORMATION

Note:

This information applies to verified customer complaints on vehicles covered under normal warranty. Refer to the SRT microfiche for warranty term information.

Warranty Type	A	
Symptom Code	53	
Damage Code	9Y	
Part Number Main Cause	9965-02-7070	
Quantity	1,2,3, OR 4	

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourseifers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership.

Bulletin No: 02-004/01R	Last Issued: 08/14/2001
Operation Number / Labor Hours	XX308XR1 / 0.5 (One tire replacement) XX308XR2 / 0.8 (Two tires replacement) XX308XR3 / 1.1 (Three tires replacement) XX308XR4 / 1.4 (Four tires replacement)